



# WD-3 Wide Angle Conversion Dome

Product Number 6430.3


## **I n s t r u c t i o n   M a n u a l**

Thank you for your purchase of Ikelite equipment. Please read this instruction manual completely before attempting to operate or dive with this product. Please refer to the back page of this manual to register your Ikelite product.

## Table of Contents


Included in the Box .....	P. 2
Attach WD-3 to 3-inch Flat Port .....	P. 3
Customer Support.....	P. 4
Limited Warranty .....	P. 4

## Included in the Box



## Attach WD-3 to 3-inch Flat Port

1. Rotate Thumbscrews counterclockwise so no threads show inside WD-3 Dome.
2. Gently push Dome over front of 3-inch Port.
3. Hand-tighten and snug both Thumbscrews. **DO NOT** over-tighten.
4. Extended areas of Dome Hood should be at the 12 and 6 o'clock positions to avoid vignetting.



## Customer Support

Ikelite Underwater Systems  
Service Department  
50 West 33rd St.  
Indianapolis, IN 46208 USA

Email: [ikelite@ikelite.com](mailto:ikelite@ikelite.com)  
Phone: 317-923-4523

## Limited Warranty

This Ikelite product is warranted against any manufacturing defects for a period of one (1) year from the original date of purchase. Defective products should be returned to Ikelite postage paid. Ikelite will, at its sole discretion, repair or replace such products, and will return to customer postage paid. All other claims of any nature are not covered. Except as mentioned above, no other warranty expressed or implied applies to this Ikelite product.



**Ikelite Underwater Systems**  
**50 West 33rd Street**  
**Indianapolis, IN 46208 USA**

**[ikelite.com](http://ikelite.com)**

© 2015 Ikelite Underwater Systems

6430.3\_WD-3\_Dome\_and\_Color\_Filter\_01-0915